COMPLETION REPORT

1	Name of Work & Job Code	Repairs to chain link fencing agn SSM wall at Shooting building Road in Mallasandra ward no 13. 013-18-000077
2	Sanctioned Estimate No & Date (AS & TS No)	BBMP/EE/PD/AS/34/17-18 Dt: 15.12.18 BBMP/CE/DZ/TS/08/17-18 Dt:26.12.18
3	Head Of Account which is Chargable	P-3176
4	Work Order No. & Date	BBMP/PD/WO/38/2017-18 Dt:28.02.2018
5	Name of Contractor	M.Lakkappa
6	Time Stipulated for completion of work	90 Days
7	Date of Commencement	BBMP/PD/WO/56/2017-18 Dt:27.03.18
8	Date of Completion	
9	Delay in execuation of Work	207 days
10	Measurement recoded in M.B Book No.	M.B No. 1902 Pg. 190107-115
11	Check Measurment of the Asst. Executive Engineer	
12	Name of the Office/Offical in charge of the Work	
13	a) Assistant Engineer	Siddrajegowda B.S
	b) Asst.Executive Engineer	Kumarappa .H

Sanctioned Estimate Amount	Amount Claims As per Actually Executed as per bills	Excess	Savings
2271,144	2270,311	—	833.

1) Certified that the above work has been completed within the stipulated time noted in the Work Order.
2) Certified that theContractor has delayed and completed the work for which necessary fine
3) Certified that the above work has been executed by the Contractor satisfactory.

Asst. Engineer Asst.Executive Engineer Executive Engineer

Scanned by CamScanner